

to engine main ground
ground
ground
ign +12V
Abe's circuit
NB CMP
NB CKP
WB O2 linear from ZT-2
converted NA CKP
converted CMP
EBC boost control
air intake temp.
water temp.
tps
WB O2
CKP
CMP
EBC boost control
ign +12V
Launch controll swi
inj.nr 3 to inj.
inj.nr 1 to inj.
inj.nr 4 to inj.
inj.nr 2 to inj.
3G to ign. side
3H to ign. side
3G to ign. side
air intake temp.
tap
inj.nr 3 to inj.
inj.nr 1 to inj.
cut cut
cut
tap
tap
tap
tap
tap
cut cut
cut
3H to ign. side
inj.nr 4 to inj.
inj.nr 2 to inj.